



SOUTH DELHI MUNICIPAL CORPORATION
PUBLIC HEALTH DEPARTMENT, WEST ZONE

Vishal Enclave, Rajouri Garden, New Delhi - 110027



No. D-783/11.01.17

Dated: 21/01/17

Health Certificate

- Name of the school Nathu Ram Convent Sr. Sec. School
- School address Shiv Ram Park, Ph-II, Nilothi More, Nangloi, New Delhi
- No of shifts One Timings: 08:00 AM to 01:30 P.M.
- No. of students :- Boys 510
319 Girls 191 Total 829
- No. of staff:- Gents 07 Ladies 23 Total 30

Accommodation provided for classroom as under:-

Floor area in the classroom is sufficient / insufficient Sufficient
 Classes are well lighted / ill lighted well lighted
 Classrooms are well ventilated / ill ventilated well ventilated
 Classes are kept / not kept neat and clean. neat and clean
 Building / classrooms require / do not require white wash etc. not required
 Drinking water is wholesome / not wholesome wholesome
 Latrine arrangement is sanitary / insanitary Sanitary

No. of toilets seats for students

One latrine-cum-urinal is required for 25 female students, so total is Sufficient
 One latrine for 40 male students is required, so total is Sufficient
 Separate toilet arrangement for staff yes/ no yes also

The overall facilities good / adequate / inadequate Adequate from health point
of view and valid upto one year from the date of issuance.
 If Building Department or any other Govt agency takes action against u/a construction or any dispute, then the Health Certificate, will be stand cancelled / revoked without any further intimation in this regard.

Manager

Smita

PRINCIPAL
NATHU RAM CONVENT SR. SEC. SCHOOL
SHIV RAM PARK, PHASE-II,
NILOTHI MORE, NANGLOI, DELHI-110041

Dy. Health Officer
West Zone
For Nathu Ram Convent School
Manager